


3310 A — LMT	Type ähnlich Herst.
10 0,3 ~	U_f I_f Heizart
P	Verw.
250 135 —	U_a U_{g_2} U_{g_1}
5,4 — 1,9 —	I_a I_{g_2} S D
$c/e =$ 4 $c/a =$	R_i R_a R_k
2,2 pF 1,5 —	$U_a \text{ max}$ $N_a \text{ max}$ $R_{g_1} \text{ max}$
—	$N_a \sim$



3310 A