

LK 4111 Va	Type Herst:
4 1,1 ~	U_f I_f Heizart
ETt — —	Verw. Kbn-Lg. Kbn-Ø
250 — — — 250 -33	U_a U_{ϱ_2} U_{ϱ_1} U_{ϱ_2} U_{ϱ_2} U_{ϱ_1}
22 —	I_a I_{ϱ_2}
2,4 18 2,4	S D R_t
1,5 6,4 —	R_k R_a R_{ϱ_2}
20 5,5 1,2	$U_{\varrho_1} \sim$ V $N_a \sim$
250 250 5 — 1	U_b max U_{ϱ_2} max N_a max N_{ϱ_2} max R_{ϱ_1} max
—	$C_{g/a}$



LK 4111