

Type Herst.	LK 8100 Va
U_f I_f Heizart	8 1,2 ~
Verw. Kbn-Lg. Kbn-Ø	Endtriode — —
U_a U_{g2} U_{g1} U_{g2} U_{g3} U_{g1}	400 — — — — —
I_a I_{g3}	30 —
S D R_t	2 13 3,75
R_b R_a R_{g3}	— — —
$U_{g1} \sim$ V $N_{g1} \sim$	— 7,8 —
U_b max U_{g2} max N_a max N_{g2} max R_{g1} max	400 — 12 — —
$C_{g/a}$	—



LK 8100