

MH 4105 Tu	Type Herst.
4 1 ~	U_I I_I Heizart
M + O — —	Verw. Kbn-Lg. Kbn-Ø
250 — — — 100 -3	U_a U_{g_5} U_{g_4} U_{g_3} U_{g_2} U_{g_1}
3,5 1,1	I_a I_{g_2}
0,52 ⁸⁾ — 360	S D R_t
— — —	R_k R_a R_{g_2}
— — —	$U_{g_1} \sim$ V $N_a \sim$
250 100 ¹⁸⁾ 1,5 0,5 3	U_b max U_{g_2} max N_a max N_{g_2} max R_{g_1} max
—	$C_{g/a}$



MH 4105