

O 40/1000 Tu	Type Herst.
10	U_f
1,1	I_f
~	Heizart
ET	Verw.
—	Kbn-Lg.
—	Kbn-Ø
1000	U_a
—	$U_{\vartheta 6}$
—	$U_{\vartheta 4}$
—	$U_{\vartheta 3}$
—	$U_{\vartheta 2}$
-90	$U_{\vartheta 1}$
50	I_a
—	$I_{\vartheta 2}$
3	S
—	D
3	R_t
2	R_k
7	R_a
—	$R_{\vartheta 2}$
—	$U_{\vartheta 1} \sim$
—	V
9	$N_a \sim$
1000	U_b max
—	$U_{\vartheta 2}$ max
40	N_a max
—	$N_{\vartheta 2}$ max
—	$R_{\vartheta 1}$ max
—	$C_{\vartheta/a}$



O 40/1000