

Type Herst.	P 30/500 Tu
$U_f$	4
$I_f$	2
Heizart	~
Verw.	ET
Kbn-Lg.	—
Kbn-Ø	—
$U_a$	500
$U_{g6}$	—
$U_{g4}$	—
$U_{g3}$	—
$U_{g2}$	—
$U_{g1}$	-150
$I_a$	60
$I_{g2}$	—
S	4
D	33
$R_t$	0,75
$R_b$	2,5
$R_c$	2,5
$R_{g2}$	—
$U_{g1} \sim$	—
V	—
$N_a \sim$	6
$U_b$ max	600
$U_{g2}$ max	—
$N_a$ max	35
$N_{g2}$ max	—
$R_{g1}$ max	—
$C_{g/a}$	—



P 30/500