

Type Herst.	P 41/800 Tu
U_f I_f Heizart	7,2 1,1 ~
Verw. Kbn-Lg. Kbn-Ø	ET — —
U_a U_{g3} U_{g4} U_{g1} U_{g2} U_{g1}	800 — — — — -80
I_a I_{g1}	40 —
S D R_t	2 14 3,5
R_b R_c R_{g1}	2 13,8 —
$U_{g1} \sim$ V $N_a \sim$	50 7,1 10
U_b max U_{g2} max N_a max N_{g1} max R_{g1} max	800 — 32 — —
$c_{g/10}$	—



P 41/800