


Type Herst.	RS 272 Te
U_f	8
I_f	1,6
Heizart	~
Verw. Kbn-Lg. Kbn-Ø	ST ³²⁾ — —
U_a	1000
$U_{\theta 6}$	—
$U_{\theta 4}$	—
$U_{\theta 3}$	—
$U_{\theta 2}$	—
$U_{\theta 1}$	-75
I_a	20 ⁷⁾ 190
$I_{\theta 2}$	35 ²⁵⁾
S	3,5
D	8
R_i	3,6
R_k	—
R_a	2,8
$R_{\theta 2}$	—
$U_{\theta 1} \sim$	220
V	12,5
$N_a \sim$	100
U_b max	1000
$U_{\theta 2}$ max	—
N_a max	100
$N_{\theta 2}$ max	—
$R_{\theta 1}$ max	—
$C_{g/a}$	5



RS 272