


Type Herst.	RS 276 Te
$U_f$ $I_f$ Heizart	10 2 ~
Verw. Kbn-Lg. Kbn-Ø	ST <sup>32)</sup> — —
$U_a$ $U_{\theta_5}$ $U_{\theta_4}$ $U_{\theta_3}$ $U_{\theta_2}$ $U_{\theta_1}$	1000 > 14 <sup>31)</sup> — — — -20
$I_a$ $I_{\theta_3}$	40 —
$S$ $D$ $R_i$	2,6 4,5 8,5
$R_k$ $R_a$ $R_{\theta_3}$	— — —
$U_{\theta_1} \sim$ $V$ $N_a \sim$	— 22 60
$U_b$ max $U_{\theta_3}$ max $N_a$ max $N_{\theta_2}$ max $R_{\theta_1}$ max	1000 — 40 — —
$C_{\theta/a}$	3,2



RS 276