


Type Herst.	RS 284 Te
U_f I_f Heizart	11 5 ~
Verw. Kbn-Lg. Kbn- \varnothing	ST ²⁴⁾ — —
U_a $U_{\vartheta 8}$ $U_{\vartheta 4}$ $U_{\vartheta 3}$ $U_{\vartheta 2}$ $U_{\vartheta 1}$	2000 — — — — -95
I_a $I_{\vartheta 3}$	15 ⁷⁾ 500 80 ²⁵⁾
S D R_i	6 5,3 3,2
R_k R_a $R_{\vartheta 3}$	— 2,35 —
$U_{\vartheta 1} \sim$ V $N_a \sim$	295 19 700
U_b max $U_{\vartheta 2}$ max N_a max $N_{\vartheta 2}$ max $R_{\vartheta 1}$ max	2500 — 400 — —
$C_{g/a}$	25,5



RS 284