


Type Herst.	RS 331 Te
U_f I_f Heizart	10 4,8 ~
Verw. Kbn-Lg. Kbn-Ø	ST ³²⁾ — —
U_a $U_{\theta 5}$ $U_{\theta 4}$ $U_{\theta 3}$ $U_{\theta 2}$ $U_{\theta 1}$	1600 — — — — -40
I_a $I_{\theta 2}$	6 ⁷⁾ 95 15 ²⁵⁾
S D R_i	1,3 — 2,56
R_k R_a $R_{\theta 2}$	— 10,5 —
$U_{\theta 1} \sim$ V $N_a \sim$	210 33 90
U_b max $U_{\theta 2}$ max N_a max $N_{\theta 2}$ max $R_{\theta 1}$ max	1600 — 75 — —
$c_{\theta/a}$	4,5



RS 331