


Type Herst.	RS 55 Te
$U_f$ $I_f$ Heizart	10 3 ~
Verw. Kbn-Lg. Kbn-Ø	ST <sup>10)</sup> 220 55
$U_a$ $U_{\theta 6}$ $U_{\theta 4}$ $U_{\theta 3}$ $U_{\theta 2}$ $U_{\theta 1}$	700 15 <sup>30)</sup> — — — -25
$I_a$ $I_{\theta 2}$	7 <sup>7)</sup> 35 4 <sup>25)</sup>
S D $R_i$	1,1 5 —
$R_k$ $R_a$ $R_{\theta 2}$	— 1,2 —
$U_{\theta 1} \sim$ V $N_a \sim$	120 20 12
$U_b$ max $U_{\theta 2}$ max $N_a$ max $N_{\theta 2}$ max $R_{\theta 1}$ max	700 — 15 — —
$c_{\theta/a}$	5,5



RS 55