


Type Herst.	RS 612 Te
U_f	5
I_f	8,5
Heizart	~
Verw. Kbn-Lg.	ST ³²⁾ 114,5 (12)
Kbn-Ø	60
U_a	2500
$U_{\theta 5}$	2 ³⁰⁾ 11 ³¹⁾
$U_{\theta 4}$	—
$U_{\theta 3}$	—
$U_{\theta 2}$	—
$U_{\theta 1}$	—
I_a	—
$I_{\theta 2}$	—
S	3,5
D	3,6
R_i	—
R_k	—
R_a	—
$R_{\theta 2}$	—
$U_{\theta 1} \sim$	—
V	28
$N_a \sim$	300
U_b max	3000
$U_{\theta 2}$ max	—
N_a max	150
$N_{\theta 2}$ max	25
$R_{\theta 1}$ max	—
$c_{\theta/a}$	2,6



RS 612