


Type Herst.	UH 4001 OL	
$U_f$	25	
$I_f$	0,1	
Heizart	$\cong$	
Verw.	H	
Kbn-Lg.	—	
Kbn- $\emptyset$	—	
$U_a$	200	
$U_{g5}$	—	
$U_{g4}$	50	
$U_{g3}$	-12	
$U_{g2}$	50	
$U_{g1}$	-2	-30
$I_a$	2	—
$I_{g3}$	2	—
$S$	0,65 <sup>3)</sup> —	
$D$	—	—
$R_i$	—	—
$R_k$	0,5	
$R_a$	—	
$R_{g2}$	—	
$U_{g1} \sim$	—	
$V$	—	
$N_a \sim$	—	
$U_b$ max	—	
$U_{g2}$ max	—	
$N_a$ max	1	
$N_{g2}$ max	—	
$R_{g1}$ max	—	
$c_{g/a}$	—	



UH 4001