


6 П 7 С = 6 П 7 6 F 6	Type ähnlich
6,3 0,9 ~	U_f I_f Heizart
STt	Verw.
250 250 -14	U_a U_{g_2} U_{g_1}
72 < 8 5,9 $g=8$	I_a I_{g_2} S D
32,5 $Ng_2 m = 3,2$ $cg/k = 11$	R_i R_a R_k
500 20 1	$U_a \text{ max}$ $N_a \text{ max}$ $R_{g_1} \text{ max}$
$cg/a = 0,6$	$N_a \sim$



6 П 7 С