

Type Herst.	DD 51 Ma
U_1 I_1 Heizart	1,5 0,067 B
Verw. Kbn-Lg. Kbn-Ø	ET — —
U_a U_{a1} U_{a2} U_{a3} U_{a4} U_{a5}	45 — — — — -3
I_a I_{a1}	1,7 —
S D R_1	0,5 20 10
R_k R_a R_{a1}	— — —
$U_{a1} \sim$ V $N_{a1} \sim$	— $g=5$ —
U_b max U_{a1} max N_a max N_{a1} max R_{a1} max	— — — — —
$c_{g/a}$	—



DD 51