

Type Herst.	FK 3 OI	
U_f I_f Heizart	4 1,5 ~	
Verw. Kbn-Lg. Kbn-Ø	Kippr. — —	
U_a U_{g_3} U_{g_4} U_{g_3} U_{g_2} U_{g_1}	800 — — — — —	
I_a I_{g_1}	5 —	
S D R_i	— — —	
R_k R_a R_{g_3}	— — —	
$U_{g_1} \sim$ V $N_a \sim$	— — —	
U_b max U_{g_2} max N_a max N_{g_2} max R_{g_1} max	800 — — — —	
$C_{g/a}$	—	



FK 3