

| Type Herst. | L 4100 Va |
|----------------|--------------|
| U_f | 4 |
| I_f | 1,1 |
| Heizart | ~ |
| Verw. | Endtriode |
| Kbn-Lg. | — |
| Kbn-Ø | — |
| U_a | 200 |
| U_{g3} | — |
| U_{g4} | — |
| U_{g2} | — |
| U_{g3} | — |
| U_{g1} | -16 |
| I_a | 12 |
| I_{g3} | — |
| S | 1,3 |
| D | 11 |
| R_t | 7 |
| R_b | 1,3 |
| R_a | 27 |
| R_{g3} | — |
| $U_{g1} \sim$ | 10,5 |
| V | 9 |
| $N_a \sim$ | 0,22 |
| U_b max | 250 |
| U_{g3} max | — |
| N_a max | 3 |
| N_{g3} max | — |
| R_{g1} max | 1 |
| $C_{g/a}$ | — |



L 4100