

LK 4100 Va	Type Herst:
4 1,1 ~	U_f I_f Heizart
Endtriode — —	Verw. Kbn-Lg. Kbn-Ø
400 — — — — -60	U_a U_{g3} U_{g4} U_{g2} U_{g3} U_{g1}
30 —	I_a I_{g3}
2 12,5 4	S D R_i
2 — —	R_k R_a R_{g3}
— 8 —	$U_{g1} \sim$ V $N_a \sim$
400 — 12 — —	U_b max U_{g2} max N_a max N_{g2} max R_{g1} max
—	$C_{g/a}$



LK 4100