

Type Herst.	LK 4140 Va
$U_f$	4
$I_f$	1,4
Heizart	~
Verw.	N
Kbn-Lg.	—
Kbn-Ø	—
$U_a$	250
$U_{\varrho 5}$	—
$U_{\varrho 4}$	—
$U_{\varrho 3}$	—
$U_{\varrho 2}$	—
$U_{\varrho 1}$	-2
$I_a$	10
$I_{\varrho 5}$	—
S	5,5
D	1,7
$R_i$	11
$R_b$	0,2
$R_a$	—
$R_{\varrho 2}$	—
$U_{\varrho 1} \sim$	—
V	60
$N_{\varrho} \sim$	—
$U_b$ max	300
$U_{\varrho 2}$ max	—
$N_a$ max	2,5
$N_{\varrho 2}$ max	—
$R_{\varrho 1}$ max	0,3
$C_{\varrho/a}$	—



LK 4140