

P 419 TuB	Type Herst.
4 0,25 ~	U_1 I_1 Heizart
N 100 44	Verw. Kbn-Lg. Kbn-Ø
160 — — — — -1	U_a U_{g5} U_{g4} U_{g3} U_{g2} U_{g1}
15 —	I_a I_{g2}
1,9 — 4,2	S D R_t
— — —	R_k R_a R_{g2}
— g=8 —	$U_{g1} \sim$ V $N_{g1} \sim$
— — 3 — —	U_b max U_{g2} max N_a max N_{g2} max R_{g1} max
—	C_g/a



P 419