

Type Herst.	P 422 TuB
U_f	4
I_f	0,25
Heizart	B
Verw.	N
Kbn-Lg.	100
Kbn-Ø	44
U_a	130
U_{g6}	—
U_{g4}	—
U_{g3}	—
U_{g2}	—
U_{g1}	-4,5
I_a	6,5
I_{g2}	—
S	2,3
D	—
R_t	5,6
R_k	—
R_a	—
R_{g2}	—
$U_{g1} \sim$	—
V	$g=13$
$N_a \sim$	—
U_b max	—
U_{g2} max	—
N_a max	3,5
N_{g2} max	—
R_{g1} max	—
$C_{g/a}$	—



P 422