


RS 247 Te	Type Herst.
10 1,7 ~	U_f I_f Heizart
ST — —	Verw. Kbn-Lg. Kbn-Ø
1000 5 ³⁰⁾ — — — -20	U_a $U_{\theta 5}$ $U_{\theta 4}$ $U_{\theta 3}$ $U_{\theta 2}$ $U_{\theta 1}$
110 —	I_a $I_{\theta 2}$
8 4 3,1	S D R_i
— — —	R_k R_a $R_{\theta 2}$
— 25 100	$U_{\theta 1} \sim$ V $N_a \sim$
1500 — 80 — —	U_b max $U_{\theta 2}$ max N_a max $N_{\theta 2}$ max $R_{\theta 1}$ max
7,5	$c_{\theta/a}$



RS 247