

Type Herst.	RS 297 Te
U_f	2
I_f	5
Heizart	~
Verw. Kbn-Lg.	ST
Kbn-Ø	—
U_a	500
U_{g5}	1 ³¹)
U_{g4}	—
U_{g3}	—
U_{g2}	—
U_{g1}	-30
I_a	80
I_{g2}	—
S	1,8
D	17
R_i	3,2
R_k	—
R_a	—
R_{g2}	—
$U_{g1} \sim$	—
V	—
$N_a \sim$	15
U_b max	800
U_{g2} max	—
N_a max	110
N_{g2} max	—
R_{g1} max	0,025
$C_{g/a}$	1,5



RS 297