


Type Herst.	RV 1,5 T 30 Te
$U_f$ $I_f$ Heizart	2 1,5 B~
Verw. Kbn-Lg. Kbn-Ø	Tr 45 —
$U_a$ $U_{\theta 5}$ $U_{\theta 4}$ $U_{\theta 3}$ $U_{\theta 2}$ $U_{\theta 1}$	200 — — — — -1,2
$I_a$ $I_{\theta 2}$	2 —
S D $R_{\xi}$	1 1,5 33
$R_k$ $R_a$ $R_{\theta 2}$	— — —
$U_{\theta 1} \sim$ V $N_a \sim$	— — —
$U_b$ max $U_{\theta 2}$ max $N_a$ max $N_{\theta 2}$ max $R_{\theta 1}$ max	200 — — — 0,5
$C_{g/a}$	—



RV 1,5 T 30