


GKe-100

Type ähnlich	ГКЭ-100 — —
U_f I_f Heizart	11 2 ~
Verw.	STt
U_a U_{g_2} U_{g_1}	1500 $U_{g_3}=250$ —
I_a I_{g_2} S D	100 — 2,5 $g=225$
R_i R_a R_k	— $c/e=15,5$ $c/a=10$
U_a max N_a max R_{g_1} max	— 80 $cg/a=0,055$
$N_a \sim$	100


ГКЭ-100